



HL7588_1102561

Part Number: **HL7588_1102561**
 Product Description: RF TXRX 4G LTE CAT4 AT&T/VERIZON
 RoHs Status: Lead free / RoHS Compliant
 Datasheets: [1.HL7588_1102561.pdf](#)
[2.HL7588_1102561.pdf](#)

Manufacturer/Brand: Sierra Wireless
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS

[SUBMIT RFQ](#)

Product details

Part Number	HL7588_1102561	Manufacturer	Sierra Wireless
Description	RF TXRX 4G LTE CAT4 AT&T/VERIZON	Lead Free Status / RoHS Status	Lead free / RoHS Compliant
Data sheet	1.HL7588_1102561.pdf2.HL7588_1102561.pdf		
Voltage - Supply	3.2 V ~ 4.5 V	Utilized IC / Part	-
Series	HL	Serial Interfaces	UART, USB
Sensitivity	-	RF Family/Standard	Cellular
Protocol	4G LTE CAT-4 (AT&T/Verizon)	Power - Output	-
Packaging	Tape & Reel (TR)	Package / Case	Module
Other Names	1102561 1645-1003-2 HL7588 V3.1 HL7588 V3.1 AT&T VERIZON 3G FALLBACK	Operating Temperature	-30°C ~ 70°C
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Modulation	-	Memory Size	-
Lead Free Status / RoHS Status	Lead free / RoHS Compliant	Frequency	850MHz, 900MHz, 1.8GHz, 1.9GHz
Data Rate	150Mbps	Current - Transmitting	650mA
Current - Receiving	-	Antenna Type	Not Included

Related Products

<p>HL7618RD_1103172 Manufacturers: Sierra Wireless Description: 4G LTE CAT1 MODULE VERIZON Download: HL7618RD_1103172.pdf</p> <p>RFQ</p>	<p>HL7588_1102498 Manufacturers: Sierra Wireless Description: RF TXRX CELLULAR 4G LTE (AT&T) Download: HL7588_1102498.pdf</p> <p>RFQ</p>
<p>HL7688_1103055 Manufacturers: Sierra Wireless Description: 4G LTE CAT1 MODULE FB HSPA+ AT&T Download: HL7688_1103055.pdf</p> <p>RFQ</p>	<p>HL7518_1103262 Manufacturers: Sierra Wireless Description: MOD HL LTE VZW Download: HL7518_1103262.pdf</p> <p>RFQ</p>
<p>HL7692_1103157 Manufacturers: Sierra Wireless Description: 4G LTE CAT1 FB GPRS DUAL-BAND EU Download: HL7692_1103157.pdf</p> <p>RFQ</p>	<p>HL7648_1103144 Manufacturers: Sierra Wireless Description: 4G LTE CAT1 MODULE AT&T Download: HL7648_1103144.pdf</p> <p>RFQ</p>
<p>HL7618_1102678 Manufacturers: Sierra Wireless Description: MOD HL LTE CAT 1 Download: HL7618_1102678.pdf</p> <p>RFQ</p>	<p>HL7648_1104116 Manufacturers: Sierra Wireless Description: RF TXRX CELL 4G LTE CAT-1 AT&T Download: HL7648_1104116.pdf</p> <p>RFQ</p>
<p>HL7692_1103454 Manufacturers: Sierra Wireless Description: MOD HL LTE W/2G FB Download: HL7692_1103454.pdf</p> <p>RFQ</p>	<p>HL7650_1103218 Manufacturers: Sierra Wireless Description: 4G LTE CAT-1 3G FB AUS Download: HL7650_1103218.pdf</p> <p>RFQ</p>
<p>HL7519_1102497 Manufacturers: Sierra Wireless Description: MOD HL LTE 1.8V Download: HL7519_1102497.pdf</p> <p>RFQ</p>	<p>HL7588_1102748 Manufacturers: Sierra Wireless Description: RF TXRX CELL 4G LTE AT&T/VERIZON Download: HL7588_1102748.pdf</p> <p>RFQ</p>

Related tags

- Sierra Wireless HL7588_1102561
- HL7588_1102561 Price
- HL7588_1102561 PDF Datasheet
- HL7588_1102561 Stock
- Sierra Wireless HL7588_1102561
- Sierra Wireless HL7588_1102561
- HL7588_1102561 Distributor
- HL7588_1102561 Pictures
- HL7588_1102561 Download Datasheet
- Buy HL7588_1102561
- Sierra Wireless Supplier
- HL7588_1102561 Supplier
- HL7588_1102561 Image
- HL7588_1102561 Datasheet
- Buy Sierra Wireless HL7588_1102561
- Sierra Wireless Distributor